

General Information

Date & Time: 18, Dec, 2025 14:46

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	6,848
Registration No.	GBE3852	Chassis No.	PA1B18F34R4253967
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	118	107	116
2	Boot Lid	110.0	108	104	118
3	Roof	96.1	108	91	90/96
4	Left Front Fender	100.0	102	97	101
5	Left Front Door	139.6	143	145	131
6	Center Panel Left				
7	Left Rear Door	107.6	108	103	112
8	Left Back Panel	112.0	126	105	105
9	Right Front Fender	102.8	95	105	108
10	Right Front Door	96.5	95	95	99
11	Center Panel Right				
12	Right Rear Door	105.0	98	106	111
13	Right Back Panel	107.0	103	102	116

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Ceiling - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal</p>	<p>Remarks (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Without warranty booklet. With spare tire, jack, tools and seat cover. 1 key. One LTO plate and one temporary plate.</p>