

General Information

Date & Time: 21, Nov, 2025 10:43

Make	Toyota	Model	Veloz
YOM	2025	Odo Meter Reading	6,736
Registration No.	NKO5669	Chassis No.	MHFAB1BY6S3134217
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	105.9	104	99	115
2	Boot Lid	96.3	104	101	84
3	Roof	115.5	129	125	100/108
4	Left Front Fender	108.0	118	102	104
5	Left Front Door	124.0	114	127	131
6	Center Panel Left				
7	Left Rear Door	118.6	117	111	128
8	Left Back Panel	139.3	147	116	155
9	Right Front Fender	107.6	110	111	102
10	Right Front Door	116.0	124	116	108
11	Center Panel Right				
12	Right Rear Door	113.3	116	107	117
13	Right Back Panel	127.6	116	123	144

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Defects not found</p>		<p>Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

Inspector Notes

With Lto plate, with spare tire and jack, 1key, no warranty booklet, no tools, scratches on headlights