

General Information

Date & Time: 24, Nov, 2025 18:57

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	22,917
Registration No.	NFC7158-1	Chassis No.	PA1B18F38P4221746
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	112	105	118
2	Boot Lid	112.6	108	109	121
3	Roof	102.9	106	100	101/105
4	Left Front Fender	102.5	111	98	99
5	Left Front Door	101.7	101	97	107
6	Center Panel Left				
7	Left Rear Door	106.0	113	104	101
8	Left Back Panel	113.0	125	106	108
9	Right Front Fender	104.6	109	103	102
10	Right Front Door	99.3	103	92	103
11	Center Panel Right				
12	Right Rear Door	109.0	105	109	113
13	Right Back Panel	108.3	106	102	117

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Grime - Small / (L) Front Floor Mat - Missing - Yes / Ceiling - Grime - Minimal / (R) Rear Trim - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Dent - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Crack, Gap - Large / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Large / Roof - Dent - Minimal / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With Lto plate, with jack and spare tire, 1key, no warranty booklet, no tools, Crack tail light, foul smell possible flooded</p>