

General Information

Date & Time: 25, Nov, 2025 17:25

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	52,062
Registration No.	NIU5759	Chassis No.	PA1B18F38R4242437
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	116	101	112
2	Boot Lid	99.9	100	99	101
3	Roof	90.3	100	91	84/87
4	Left Front Fender	97.2	99	93	100
5	Left Front Door	101.3	103	108	93
6	Center Panel Left				
7	Left Rear Door	104.3	105	105	103
8	Left Back Panel	101.7	112	101	92
9	Right Front Fender	98.5	103	95	98
10	Right Front Door	100.0	101	98	101
11	Center Panel Right				
12	Right Rear Door	94.8	93	94	98
13	Right Back Panel	100.1	93	105	102

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	E	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Large / (R) Rear Trim - Grime - Medium / (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Large / (L) Rear Trim - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (L) Front Seat - Grime - Small / Steering Wheel - Worn, Peel, Crack - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Minimal</p>		<p>Remarks Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Medium / Roof - Scratch - Minimal</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>	

Inspector Notes
with LTO plate/with spare tire/with spare key/with warranty booklet/reverse camera not working/No jack and incomplete tools/ No fog light /interior dirty