

General Information

Date & Time: 26, Nov, 2025 12:38

Make	Toyota	Model	Vios
YOM	2026	Odo Meter Reading	1,028
Registration No.	DCA8551	Chassis No.	PA1B18F38S4295015
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.3	117	100	108
2	Boot Lid	103.6	102	101	108
3	Roof	98.3	102	100	95/97
4	Left Front Fender	100.6	99	100	103
5	Left Front Door	100.2	100	102	99
6	Center Panel Left				
7	Left Rear Door	110.6	119	109	104
8	Left Back Panel	108.6	114	111	101
9	Right Front Fender	102.1	106	98	102
10	Right Front Door	103.4	108	98	104
11	Center Panel Right				
12	Right Rear Door	101.7	97	99	110
13	Right Back Panel	102.3	102	103	102

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	A
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes</p>	

Inspector Notes

with LTO plate/with spare tire/with spare key/with warranty booklet/with reverse camera /with jack and incomplete tools