

General Information

Date & Time: 25, Nov, 2025 18:33

Make	Toyota	Model	Avanza
YOM	2023	Odo Meter Reading	130,532
Registration No.	NHB6354	Chassis No.	MHFAA1BY4N0006678
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	95.8	77	111	99
2	Boot Lid	110.5	116	121	95
3	Roof	104.1	110	100	98/108
4	Left Front Fender	153.3	168	151	141
5	Left Front Door	118.0	113	115	126
6	Center Panel Left				
7	Left Rear Door	118.3	122	111	122
8	Left Back Panel	107.6	115	104	104
9	Right Front Fender	130.0	125	124	141
10	Right Front Door	112.6	118	111	109
11	Center Panel Right				
12	Right Rear Door	118.3	126	113	116
13	Right Back Panel	112.6	125	101	112

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / Dashboard - Worn, Scratch, Cut, Crack - Small / Trunk Room - Worn, Scratch, Cut, Crack - Medium / (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / Steering Wheel - Worn, Peel, Crack - Medium / Ceiling - Grime - Medium</p>	<p>Remarks (R) Rear Fender, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/ No spare key/with reverse camera/with jack No tools/fog light issue/No warranty booklets/plate light issue/interior dirty</p>