

General Information

Date & Time: 25, Nov, 2025 17:21

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	22,890
Registration No.	NKG3599	Chassis No.	PA1B18F31R4275019
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	115	99	116
2	Boot Lid	106.3	109	105	105
3	Roof	95.4	97	89	94/102
4	Left Front Fender	101.2	101	98	105
5	Left Front Door	95.4	100	93	93
6	Center Panel Left				
7	Left Rear Door	108.3	111	101	113
8	Left Back Panel	114.0	129	102	111
9	Right Front Fender	96.8	103	94	93
10	Right Front Door	102.3	100	105	102
11	Center Panel Right				
12	Right Rear Door	102.1	108	101	97
13	Right Back Panel	105.8	96	106	116

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Minimal / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Minimal / Console, Switches, Vents - Worked - Minimal / (L) Front Floor Mat - Grime - Minimal / Overall Interior - Smell - Yes / Trunk Room - Worked - Minimal / Dashboard - Worked - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Rear Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Small / Roof - Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / Bonnet, Headlight - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with manual booklet, with reverse camera, with spare tire, with jack, no tools, no spare key, no warranty booklet, scratches on taillight</p>