

## General Information

Date & Time: 27, Nov, 2025 15:41

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	4,055
<b>Registration No.</b>	NKQ3801	<b>Chassis No.</b>	PA1B18F34S4290278
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.6	145	100	123
2	Boot Lid	118.3	107	132	116
3	Roof	112.5	119	106	118/107
4	Left Front Fender	105.0	102	105	108
5	Left Front Door	106.0	103	108	107
6	Center Panel Left				
7	Left Rear Door	113.0	114	117	108
8	Left Back Panel	108.3	112	108	105
9	Right Front Fender	111.3	115	106	113
10	Right Front Door	139.6	167	133	119
11	Center Panel Right				
12	Right Rear Door	121.3	120	108	136
13	Right Back Panel	115.3	112	105	129

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

