

## General Information

Date & Time: 26, Nov, 2025 16:01

<b>Make</b>	Mitsubishi	<b>Model</b>	Mirage
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	21,071
<b>Registration No.</b>	CCB3721	<b>Chassis No.</b>	PAEA13TJPPA010792
<b>CC</b>	1.2	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.6	129	119	129
2	Boot Lid	108.0	103	117	104
3	Roof	98.8	106	100	94/96
4	Left Front Fender	114.3	116	106	121
5	Left Front Door	110.3	113	110	108
6	Center Panel Left				
7	Left Rear Door	105.6	105	102	110
8	Left Back Panel	125.0	130	127	118
9	Right Front Fender	106.0	104	101	113
10	Right Front Door	109.6	108	109	112
11	Center Panel Right				
12	Right Rear Door	105.0	106	101	108
13	Right Back Panel	120.0	119	122	119

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

