

General Information

Date & Time: 14, Jan, 2026 15:59

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	43,187
Registration No.	CBD2904	Chassis No.	PA1B18F30N4177500
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	115	109	120
2	Boot Lid	153.0	169	138	152
3	Roof	91.4	100	92	86/88
4	Left Front Fender	335.6	227	657	123
5	Left Front Door	166.0	169	158	171
6	Center Panel Left				
7	Left Rear Door	168.6	202	154	150
8	Left Back Panel	182.6	191	169	188
9	Right Front Fender	99.6	102	101	96
10	Right Front Door	101.1	98	102	103
11	Center Panel Right				
12	Right Rear Door	102.8	97	100	112
13	Right Back Panel	102.6	103	101	104

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (L) Front Fender - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Mirror - Crack - Damaged / (L) Front Fender, Molding - Scratch & Dent - Medium / (R) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, no spare tire, no jack and tools, scratches on headlight and taillight, cover under engine missing, check engine</p>