

General Information

Date & Time: 15, Jan, 2026 13:59

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	18,165
Registration No.	BAG7316	Chassis No.	PA1B18F38R4273560
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	123	121	115
2	Boot Lid	112.3	111	107	119
3	Roof	103.8	106	102	96/112
4	Left Front Fender	99.8	102	99	99
5	Left Front Door	104.6	97	111	106
6	Center Panel Left				
7	Left Rear Door	110.6	109	107	116
8	Left Back Panel	113.6	114	110	117
9	Right Front Fender	109.3	110	111	107
10	Right Front Door	104.3	104	106	103
11	Center Panel Right				
12	Right Rear Door	110.6	119	103	110
13	Right Back Panel	107.6	106	108	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Trunk Room - Loose, Deformed - Large / (L) Front Trim - Grime - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with jack, 2keys, no spare tire and tools, trunk cover missing, warning lamp issue</p>