

## General Information

Date & Time: 03, Dec, 2025 13:37

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	12,156
<b>Registration No.</b>	DBQ8675	<b>Chassis No.</b>	PA1B18F35R4262225
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>117.3</b>	125	112	115
2	Boot Lid	<b>111.3</b>	114	104	116
3	Roof	<b>110.0</b>	116	105	116/103
4	Left Front Fender	<b>111.0</b>	109	104	120
5	Left Front Door	<b>109.6</b>	111	109	109
6	Center Panel Left				
7	Left Rear Door	<b>109.3</b>	116	112	100
8	Left Back Panel	<b>115.0</b>	122	119	104
9	Right Front Fender	<b>114.3</b>	122	112	109
10	Right Front Door	<b>118.6</b>	115	116	125
11	Center Panel Right				
12	Right Rear Door	<b>115.3</b>	111	118	117
13	Right Back Panel	<b>114.3</b>	104	113	126

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

