

General Information

Date & Time: 03, Dec, 2025 15:53

Make	Toyota	Model	Fortuner
YOM	2023	Odo Meter Reading	30,723
Registration No.	NHN5303	Chassis No.	MHFCB8GS7N0528627
CC	2.4	Transmission	M/T
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.6	119	125	106
2	Boot Lid	104.2	92	128	93
3	Roof	124.2	136	142	113/106
4	Left Front Fender	104.9	100	101	114
5	Left Front Door	104.0	112	104	96
6	Center Panel Left				
7	Left Rear Door	92.7	105	89	84
8	Left Back Panel	107.0	114	106	101
9	Right Front Fender	112.3	124	108	105
10	Right Front Door	112.0	111	110	115
11	Center Panel Right				
12	Right Rear Door	104.3	99	103	111
13	Right Back Panel	116.3	113	113	123

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small</p>		<p>Remarks Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / Bonnet, Headlight - Scratch & Dent - Small / Roof - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>With LTO plate and warranty booklet, No Spare tire and Jack and Tools, No Spare key, Scratch headlight and tail light, Worn Tires, adhesive marks on vehicle, horn issue, foul smell.</p>