

General Information

Date & Time: 03, Dec, 2025 09:59

Make	Kia	Model	Seltos
YOM	2024	Odo Meter Reading	2,156
Registration No.	NKT3258	Chassis No.	LJD5AA19BR0117881
CC	1.4	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.3	141	131	125
2	Boot Lid	113.3	103	123	114
3	Roof	192.5	172	192	199/207
4	Left Front Fender	139.6	120	151	148
5	Left Front Door	136.6	143	129	138
6	Center Panel Left				
7	Left Rear Door	146.3	130	167	142
8	Left Back Panel	134.0	144	133	125
9	Right Front Fender	125.6	127	137	113
10	Right Front Door	126.3	129	127	123
11	Center Panel Right				
12	Right Rear Door	131.3	123	135	136
13	Right Back Panel	135.0	126	138	141

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal / Ceiling - Grime - Minimal / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Minimal / Console, Switches, Vents - Worked - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Crack, Gap - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Roof - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with reverse camera, with warranty & manual booklet, with spare key, with spare tire, scratches on taillight, possible repainted, no tools & jack.</p>