

General Information

Date & Time: 03, Dec, 2025 15:48

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	11,601
Registration No.	NJE4732	Chassis No.	PA1B18F30S4283649
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	124	112	107
2	Boot Lid	108.4	113	99	113
3	Roof	98.1	99	97	99/97
4	Left Front Fender	98.2	106	96	93
5	Left Front Door	106.3	109	107	103
6	Center Panel Left				
7	Left Rear Door	101.5	101	112	92
8	Left Back Panel	114.6	113	111	120
9	Right Front Fender	93.9	99	91	93
10	Right Front Door	101.8	102	100	104
11	Center Panel Right				
12	Right Rear Door	110.3	107	111	113
13	Right Back Panel	113.0	117	110	112

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Steering Wheel - Worn, Peel, Crack - Small</p>	<p>Remarks Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate, No warranty booklet and Spare tire and Jack and Tools, No Spare key, Scratch headlight and tail light, Worn Tires, foul smell, Abnormal shiftshock and vibration,</p>