

General Information

Date & Time: 13, Dec, 2025 10:17

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	25,514
Registration No.	CCF1210	Chassis No.	PA1B18F38R4259416
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.8	102	112	95
2	Boot Lid	105.3	100	108	108
3	Roof	91.8	90	93	94/91
4	Left Front Fender	94.3	94	97	91
5	Left Front Door	93.7	91	95	96
6	Center Panel Left				
7	Left Rear Door	100.6	111	99	92
8	Left Back Panel	102.3	102	102	103
9	Right Front Fender	100.9	103	100	100
10	Right Front Door	101.7	99	108	98
11	Center Panel Right				
12	Right Rear Door	101.6	107	99	99
13	Right Back Panel	104.9	102	96	117

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	B
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small</p>		<p>Remarks Member (Bolted) - Dent - Yes / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Roof - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	B
<p>Remarks Defects not found</p>		<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>With LTO plate and warranty booklet, No Spare tire and Jack and Tools, No Spare key, Scratch and Crack Tail light and Headlight, worn tires, foul smell, Abnormal vibration, Abnormal shift shock.</p>