

General Information

Date & Time: 09, Dec, 2025 12:23

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	15,299
Registration No.	BAG3008	Chassis No.	PA1B18F32R4250002
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	120.3	125	109	127
2	Boot Lid	112.0	112	107	117
3	Roof	103.4	104	108	99/103
4	Left Front Fender	108.2	115	96	114
5	Left Front Door	111.0	112	109	112
6	Center Panel Left				
7	Left Rear Door	116.0	111	111	126
8	Left Back Panel	120.3	129	118	114
9	Right Front Fender	103.8	111	100	101
10	Right Front Door	105.6	105	100	112
11	Center Panel Right				
12	Right Rear Door	107.6	109	104	110
13	Right Back Panel	109.3	106	106	116

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Large / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks Trunk Hood, Rear Gate - Scratch - Large / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/right side tail light cover small crack/with jack and incomplete tools/with warranty booklet/with reverse camera</p>