

General Information

Date & Time: 10, Dec, 2025 15:47

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	2,884
Registration No.	NHH5778	Chassis No.	PA1B18F38R4240011
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	106	102	123
2	Boot Lid	107.3	107	104	111
3	Roof	127.5	137	137	127/109
4	Left Front Fender	99.6	97	97	105
5	Left Front Door	100.8	100	103	100
6	Center Panel Left				
7	Left Rear Door	113.0	117	112	110
8	Left Back Panel	119.0	108	115	134
9	Right Front Fender	109.0	115	104	108
10	Right Front Door	99.0	101	96	100
11	Center Panel Right				
12	Right Rear Door	109.6	109	111	109
13	Right Back Panel	111.3	104	106	124

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Dashboard - Worked - Minimal / (L) Front Seat - Grime - Minimal / Trunk Room - Worked - Minimal / (R) Front Seat - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Front Trim - Grime - Minimal / Rear Seat - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal / Ceiling - Grime - Minimal</p>	<p>Remarks Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Small / Roof - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with manual booklet, with spare, with spare key, with jack, with reverse camera, no tools, no warranty booklet, scratches on taillight.</p>