

General Information

Date & Time: 09, Dec, 2025 15:36

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	1,666
Registration No.	NHQ6038	Chassis No.	PA1B18F30R4249219
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.3	119	105	119
2	Boot Lid	95.9	93	97	98
3	Roof	104.6	108	110	94/107
4	Left Front Fender	553.3	399	994	267
5	Left Front Door	100.5	102	100	100
6	Center Panel Left				
7	Left Rear Door	107.4	123	100	99
8	Left Back Panel	106.2	109	110	100
9	Right Front Fender	106.0	112	106	100
10	Right Front Door	104.0	104	101	107
11	Center Panel Right				
12	Right Rear Door	105.0	103	97	115
13	Right Back Panel	106.6	110	104	106

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Small</p>	<p>Remarks (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/with spare key/with reverse camera/with jack and incomplete tools/No warranty booklet</p>