

General Information

Date & Time: 10, Dec, 2025 15:50

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	1,499
Registration No.	NFR5392	Chassis No.	PA1B18F30R4248507
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	96	119	117
2	Boot Lid	112.6	108	116	114
3	Roof	103.7	105	100	100/110
4	Left Front Fender	104.3	112	98	103
5	Left Front Door	101.1	102	99	103
6	Center Panel Left				
7	Left Rear Door	108.3	121	105	99
8	Left Back Panel	107.0	111	107	103
9	Right Front Fender	97.6	98	100	95
10	Right Front Door	104.0	108	103	101
11	Center Panel Right				
12	Right Rear Door	107.8	100	101	123
13	Right Back Panel	111.3	111	104	119

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Door, Molding - Dent - Small / (L) Rear Door, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ no LTO plate/ incomplete tools/ with jack, and spare tire/</p>