

General Information

Date & Time: 12, Jan, 2026 18:54

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	24,079
Registration No.	NJA4452	Chassis No.	MHFAA1BY6R0037923
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	112	107	113
2	Boot Lid	106.2	114	107	98
3	Roof	111.0	122	121	101/100
4	Left Front Fender	105.3	108	101	107
5	Left Front Door	116.6	107	117	126
6	Center Panel Left				
7	Left Rear Door	110.6	112	106	114
8	Left Back Panel	115.3	120	104	122
9	Right Front Fender	106.1	109	110	99
10	Right Front Door	112.0	120	108	108
11	Center Panel Right				
12	Right Rear Door	109.9	113	100	117
13	Right Back Panel	110.3	114	102	115

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / Rear Seat - Grime - Small / Console, Switches, Vents - Loose, Deformed - Medium</p>	<p>Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With Lto plate, with warranty booklet, with spare tire and jack, 2keys, no tools, scratches on headlight, possible flooding, foul smell</p>