

General Information

Date & Time: 10, Dec, 2025 16:03

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	26,558
Registration No.	NJF3809	Chassis No.	MHFAA1BY8R0035073
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	99	103	110
2	Boot Lid	105.6	106	113	98
3	Roof	127.2	120	117	163/109
4	Left Front Fender	99.5	97	103	99
5	Left Front Door	114.0	111	112	119
6	Center Panel Left				
7	Left Rear Door	110.3	104	107	120
8	Left Back Panel	114.3	118	96	129
9	Right Front Fender	99.0	99	104	94
10	Right Front Door	108.3	112	109	104
11	Center Panel Right				
12	Right Rear Door	106.6	105	107	108
13	Right Back Panel	112.3	108	118	111

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small / Mat Other - Grime - Minimal / (R) Front Floor Mat - Grime - Minimal</p>		<p>Remarks (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal / Roof - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small</p>	
<p>Frame Evaluation :</p>		<p>Functional Evaluation :</p>	
A		A	
<p>Remarks Defects not found</p>		<p>Remarks Spare Key - Issue - Unexist</p>	

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire, No Tools and Jack and Warranty booklet, No spare key, worn tires, foul smell, Scratch Headlight and tail light, warning lamps on maintenance, plate light and Room light issue.</p>