

## General Information

Date & Time: 11, Dec, 2025 15:57

<b>Make</b>	Toyota	<b>Model</b>	Innova
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	47,880
<b>Registration No.</b>	NKF4635	<b>Chassis No.</b>	PA2JA8EM1R0147887
<b>CC</b>	2.8	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Wagon
<b>Colour</b>	Blackish Red Mica		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.8	110	94	117
2	Boot Lid	110.3	113	112	106
3	Roof	102.4	95	103	110/102
4	Left Front Fender	99.7	93	105	101
5	Left Front Door	105.7	92	112	113
6	Center Panel Left				
7	Left Rear Door	106.6	105	111	104
8	Left Back Panel	108.0	108	107	109
9	Right Front Fender	101.8	96	101	109
10	Right Front Door	93.6	94	94	93
11	Center Panel Right				
12	Right Rear Door	96.7	98	98	94
13	Right Back Panel	109.6	111	102	116

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

