

General Information

Date & Time: 13, Dec, 2025 13:18

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	3,093
Registration No.	GBK5091	Chassis No.	MHFAA1BY1S0043523
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.3	116	114	122
2	Boot Lid	111.6	116	118	101
3	Roof	125.7	133	124	122/124
4	Left Front Fender	107.0	108	103	110
5	Left Front Door	126.0	117	127	134
6	Center Panel Left				
7	Left Rear Door	119.6	125	115	119
8	Left Back Panel	124.0	138	119	115
9	Right Front Fender	112.6	117	114	107
10	Right Front Door	117.0	123	116	112
11	Center Panel Right				
12	Right Rear Door	117.0	119	110	122
13	Right Back Panel	115.6	107	111	129

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small	Remarks (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With warranty booklet, spare tire, jack and seat cover. Without tools. 1 key. No LTO plate.