

General Information

Date & Time: 13, Dec, 2025 12:31

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	23,093
Registration No.	GBC9705	Chassis No.	PA1B18F31P4232409
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	121	110	116
2	Boot Lid	109.0	104	110	113
3	Roof	101.1	100	103	99/103
4	Left Front Fender	99.8	101	96	103
5	Left Front Door	105.6	105	112	100
6	Center Panel Left				
7	Left Rear Door	108.3	107	105	113
8	Left Back Panel	110.3	117	107	107
9	Right Front Fender	110.3	110	110	111
10	Right Front Door	103.6	102	109	100
11	Center Panel Right				
12	Right Rear Door	103.0	103	101	105
13	Right Back Panel	113.3	106	109	125

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (L) Front Floor Mat - Worked - Small	Remarks Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Front Windshield - Damaged - Large / Roof - Scratch & Dent - Medium
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

Damaged front windshield. Without warranty booklet. With spare tire, jack, tools and leather seat cover. 2 keys. With LTO plate.