

General Information

Date & Time: 11, Dec, 2025 16:04

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	41,379
Registration No.	CCA2614	Chassis No.	PA1B18F39P4223201
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.3	114	101	107
2	Boot Lid	111.0	106	109	118
3	Roof	91.1	91	93	87/93
4	Left Front Fender	98.3	104	97	94
5	Left Front Door	101.1	102	99	102
6	Center Panel Left				
7	Left Rear Door	96.7	101	93	96
8	Left Back Panel	102.3	103	103	101
9	Right Front Fender	95.6	96	96	95
10	Right Front Door	96.7	99	92	99
11	Center Panel Right				
12	Right Rear Door	96.9	95	94	102
13	Right Back Panel	102.3	100	101	106

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Trim - Worked - Small / (L) Front Floor Mat - Worked - Small / (R) Front Trim - Worked - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small / Overall Interior - Smell - Yes / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal	Remarks Member (Bolted) - Dent - Yes / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Small / Bonnet, Headlight - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Shift Shock - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Lamps (Brake, Tail, Fog) - Issue - Yes / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
With LTO plate and Sparetire, Jack and Incomplete Tools, No warranty booklet, No spare key, no reverse camera, foul smell, possible flooded, warning lamps on, Aircon issue, Abnormal vibration, Abnormal shiftshock, Abnormal noise, scratch headlight and tail light, tail light busted.