


General Information

Date & Time: 17, Dec, 2025 10:43

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	13,494
Registration No.	NKQ9777	Chassis No.	PAHAD9DA4S1626749
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	Dropside
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.0	102	112	110
2	Boot Lid	66.4	65	66	68
3	Roof	137.7	152	121	145/133
4	Left Front Fender	114.6	116	111	117
5	Left Front Door	99.5	103	100	96
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	85.6	82	94	81
9	Right Front Fender	114.3	113	115	115
10	Right Front Door	99.3	100	98	101
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	80.4	82	83	76

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Worked - Small</p>	<p>Remarks (L) Side Gate - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch & Dent - Small / Cargo Bed Floor - Scratch - Medium / Roof - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With Sparetire and Jack and Incomplete Tools, No warranty booklet and LTO Plate, scratch headlight and tail light, no reverse camera, reverse light issue.</p>