

General Information

Date & Time: 14, Jan, 2026 11:26

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	21,978
Registration No.	BAF8530	Chassis No.	PA1B18F31R4243400
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.3	121	116	115
2	Boot Lid	121.6	132	105	128
3	Roof	112.2	123	106	107/113
4	Left Front Fender	104.3	109	100	104
5	Left Front Door	109.6	108	109	112
6	Center Panel Left				
7	Left Rear Door	111.6	111	116	108
8	Left Back Panel	110.6	118	106	108
9	Right Front Fender	113.6	118	113	110
10	Right Front Door	110.0	110	110	110
11	Center Panel Right				
12	Right Rear Door	113.6	112	109	120
13	Right Back Panel	110.6	111	110	111

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Knobs - Worn, Peel, Crack - Medium	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
With Lto plate, with jack, 2keys, no warranty booklet, no spare tire and tools, scratches on headlight and taillight