

## General Information

Date & Time: 12, Dec, 2025 15:40

<b>Make</b>	Mitsubishi	<b>Model</b>	Adventure
<b>YOM</b>	2017	<b>Odo Meter Reading</b>	118,312
<b>Registration No.</b>	CAD2314	<b>Chassis No.</b>	PAEVB5NHHMB0116505
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Wagon
<b>Colour</b>	Black		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	82.1	86	75	86
2	Boot Lid	88.1	93	86	85
3	Roof	100.8	93	86	102/122
4	Left Front Fender	105.6	108	102	107
5	Left Front Door	95.5	94	98	94
6	Center Panel Left				
7	Left Rear Door	99.1	102	93	102
8	Left Back Panel	103.0	104	101	104
9	Right Front Fender	102.8	104	97	108
10	Right Front Door	90.7	97	89	87
11	Center Panel Right				
12	Right Rear Door	93.9	94	94	95
13	Right Back Panel	97.5	95	90	108

Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>E</b>	<b>Exterior Evaluation :</b>	<b>E</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Worked - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / (R) Front Seat - Worn - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Overall Interior - Animal Hair - Yes / Ceiling - Grime - Large / Rear Seat - Grime - Large / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Small / Console, Switchs, Vents - Traces of Adhesive Tape - Yes / Glove Box - Loose, Deformed - Small / Dashboard - Worn, Scratch, Cut, Crack - Small / Dashboard - Traces of Adhesive Tape - Yes / Steering Wheel - Worn, Peel, Crack - Small / Room Mirror - Stuck - Yes / Instrument Panel - Worn, Scratch, Cut, Crack - Small</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch &amp; Dent - Medium</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Door Lock - Issue - Yes / Battery - Weak - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
<p>With LTO plate and Sparetire, Warranty booklet, No spare key, no reverse camera, No Tools and Jack, Scratch and Crack Tail light and Headlight, foglight issue, plate light issue and room light issue, headlight issue, Worn tires and Sparetire, Foul smell, possible flooded, door issue left rear.</p>