


## General Information

Date & Time: 12, Dec, 2025 15:35

|                         |           |                          |                   |
|-------------------------|-----------|--------------------------|-------------------|
| <b>Make</b>             | Toyota    | <b>Model</b>             | Vios              |
| <b>YOM</b>              | 2024      | <b>Odo Meter Reading</b> | 24,672            |
| <b>Registration No.</b> | DBN3037-1 | <b>Chassis No.</b>       | PA1B18F33P4230452 |
| <b>CC</b>               | 1.3       | <b>Transmission</b>      | CVT               |
| <b>Fuel Type</b>        | Gas       | <b>Type of Body</b>      | Sedan             |
| <b>Colour</b>           | Green     |                          |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 106.3         | 110    | 104    | 105      |
| 2  | Boot Lid           | 486.0         | 172    | 1,106  | 180      |
| 3  | Roof               | 89.8          | 97     | 94     | 85/84    |
| 4  | Left Front Fender  | 97.1          | 99     | 89     | 104      |
| 5  | Left Front Door    | 98.5          | 98     | 100    | 98       |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     | 97.8          | 100    | 96     | 98       |
| 8  | Left Back Panel    | 105.9         | 120    | 100    | 98       |
| 9  | Right Front Fender | 94.3          | 97     | 91     | 95       |
| 10 | Right Front Door   | 89.3          | 105    | 93     | 70       |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 94.9          | 96     | 92     | 97       |
| 13 | Right Back Panel   | 105.6         | 97     | 97     | 123      |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

|                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>                                                                                                                                                                                                                                                                                                                                                                                                                                                          | <b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|  <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>                                                                                                                                                                                                                                                                                                        |  <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| <p><b>Remarks</b><br/>Overall Interior - Smell - Yes / Ceiling - Grime - Small / (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Rear Seat - Cigarette Burns - Burnt / Rear Seat - Grime - Small / (R) Front Seat - Worn - Yes / (L) Front Seat - Cut, Crack - Medium / (L) Front Seat - Cigarette Burns - Burnt Minimal / Dashboard - Traces of Adhesive Tape - Yes / Console, Switches, Vents - Loose, Deformed - Small</p> | <p><b>Remarks</b><br/>(R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Member (Bolted) - Dent - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / (L) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Repair mark - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch &amp; Dent - Small / Roof - Scratch &amp; Dent - Small / (R) Mirror - Scratch - Minimal / (L) Mirror - Scratch - Minimal</p> |
| <b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>                                                                                                                                                                                                                                                                                                                                                                                                                                                             | <b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| <p><b>Remarks</b><br/>Front Cross Member Support - Condition of Welding ? - Yes</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                       | <p><b>Remarks</b><br/>Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Battery - Weak - Yes / Parking Brake - Function - Weak / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |

|                                                                                                                                                                                                                                                                                                                            |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <p><b>Inspector Notes</b></p>                                                                                                                                                                                                                                                                                              |
| <p>With LTO plate, No warranty booklet and Sparetire, No Tools and Jack, No Spare key, Scratch and Crack Tail light and Headlight, worn tires, adhesive marks on vehicle, foul smell, possible flooded, warning lamps on, headlight issue, plate light and Room light issue, air-conditioned issue, no reverse camera.</p> |