

General Information

Date & Time: 15, Dec, 2025 15:57

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	45,676
Registration No.	NIH4345	Chassis No.	PA1B18F35N4199458
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	182.0	186	197	163
2	Boot Lid	98.1	102	93	100
3	Roof	103.3	104	98	116/96
4	Left Front Fender	90.6	84	92	96
5	Left Front Door	104.2	104	110	99
6	Center Panel Left				
7	Left Rear Door	103.4	104	99	107
8	Left Back Panel	104.4	113	102	98
9	Right Front Fender	93.6	97	92	92
10	Right Front Door	101.3	104	100	100
11	Center Panel Right				
12	Right Rear Door	98.8	99	96	101
13	Right Back Panel	103.7	94	98	119

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Cigarette Burns - Burnt, Hole / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / Dashboard - Worked - Minimal / Console, Switches, Vents - Worked - Minimal / (R) Front Seat - Grime - Small / Trunk Room - Worked - Minimal / Mat Other - Grime - Small	Remarks Bonnet - Repair Traces - Yes / (L) Front Fender, Molding - Crack, Gap - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Dent - Medium / Roof - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / Bonnet, Headlight - Repair mark - Yes / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Repair mark - Yes / Rear Bumper, Lamps, Panels - Repair mark - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate, with spare tire, with jack, no tools, no reverse camera, no warranty & manual booklet, no spare key, scratches on tailight & headlight.