

General Information

Date & Time: 19, Jan, 2026 10:28

Make	Ford	Model	Ranger
YOM	2024	Odo Meter Reading	27,653
Registration No.	CBB9466	Chassis No.	MPBUMFE90PX538213
CC	2.0	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.0	113	130	114
2	Boot Lid	105.3	108	103	105
3	Roof	122.2	128	133	120/108
4	Left Front Fender	125.3	121	134	121
5	Left Front Door	118.6	122	113	121
6	Center Panel Left				
7	Left Rear Door	110.3	109	104	118
8	Left Back Panel	105.9	106	121	91
9	Right Front Fender	128.0	121	135	128
10	Right Front Door	119.6	124	116	119
11	Center Panel Right				
12	Right Rear Door	115.0	115	115	115
13	Right Back Panel	105.3	96	121	99

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Ceiling - Grime - Minimal / (R) Front Seat - Worn - Yes / Overall Interior - Smell - Yes</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Side Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch - Minimal / (L) Side Gate - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / Bonnet, Headlight - Scratch & Dent - Minimal / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>no warranty booklet, jack and tools, with spare tire, with LTO plate, scratches on tail light</p>