


General Information

Date & Time: 15, Dec, 2025 11:46

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	55,671
Registration No.	NIS8403-1	Chassis No.	PA1B18F37P4230079
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	117	106	113
2	Boot Lid	129.3	102	148	138
3	Roof	100.2	104	103	94/100
4	Left Front Fender	219.0	187	282	188
5	Left Front Door	152.6	168	133	157
6	Center Panel Left				
7	Left Rear Door	162.0	193	148	145
8	Left Back Panel	154.0	160	155	147
9	Right Front Fender	164.3	161	153	179
10	Right Front Door	135.3	141	126	139
11	Center Panel Right				
12	Right Rear Door	168.0	182	134	188
13	Right Back Panel	158.0	156	160	158

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Trunk Room - Loose, Deformed - Medium</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / Front Windshield - Scratch, Stone chip - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With Lto plate, with spare tire, 2 keys, no warranty booklet, no jack and tools, windshield issue</p>