

## General Information

Date & Time: 20, Dec, 2025 13:18

<b>Make</b>	Mitsubishi	<b>Model</b>	Mirage
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	1,447
<b>Registration No.</b>	CCJ6681	<b>Chassis No.</b>	PAEA13RXSSA001319
<b>CC</b>	1.2	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Gray		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	<b>127.0</b>	133	124	124
2	Boot Lid	<b>103.7</b>	96	114	101
3	Roof	<b>104.5</b>	103	105	105/105
4	Left Front Fender	<b>106.0</b>	109	105	104
5	Left Front Door	<b>105.0</b>	105	102	108
6	Center Panel Left				
7	Left Rear Door	<b>106.3</b>	110	101	108
8	Left Back Panel	<b>118.0</b>	119	122	113
9	Right Front Fender	<b>107.6</b>	106	102	115
10	Right Front Door	<b>112.6</b>	112	110	116
11	Center Panel Right				
12	Right Rear Door	<b>108.3</b>	104	105	116
13	Right Back Panel	<b>114.6</b>	104	117	123

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	B	<b>Exterior Evaluation :</b>	B
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Overall Interior - Animal Hair - Yes</p>		<p><b>Remarks</b> (L) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Bonnet, Headlight - Scratch - Minimal</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Defects not found</p>	

<b>Inspector Notes</b>
no tools/ with warranty booklet and LTO plate/ with jack and spare tire/