

General Information

Date & Time: 05, Jan, 2026 09:01

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	15,943
Registration No.	DBR8724	Chassis No.	PAEL65MYSRB027479
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	71.6	72	69	74
2	Boot Lid	94.3	111	89	83
3	Roof	74.8	75	65	89/71
4	Left Front Fender	84.0	74	95	83
5	Left Front Door	68.0	67	67	70
6	Center Panel Left	78.5	80	79	76
7	Left Rear Door				
8	Left Back Panel	107.5	100	95	128
9	Right Front Fender	95.4	100	86	100
10	Right Front Door	65.3	66	65	65
11	Center Panel Right	84.8	75	105	75
12	Right Rear Door				
13	Right Back Panel	114.9	89	139	117

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

