

General Information

Date & Time: 22, Dec, 2025 14:43

Make	Mazda	Model	BT50
YOM	2023	Odo Meter Reading	9,144
Registration No.	FAP3010	Chassis No.	MP2TFS40JNT031153
CC	3.0	Transmission	A/T
Fuel Type	Diesel	Type of Body	Double Cab. Pick-Up
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	156.0	146	162	160
2	Boot Lid	125.6	126	124	127
3	Roof	116.0	104	125	116/119
4	Left Front Fender	148.0	155	152	137
5	Left Front Door	128.3	126	127	132
6	Center Panel Left				
7	Left Rear Door	125.0	127	125	123
8	Left Back Panel	128.0	133	123	128
9	Right Front Fender	119.3	119	112	127
10	Right Front Door	128.3	136	127	122
11	Center Panel Right				
12	Right Rear Door	125.3	120	125	131
13	Right Back Panel	121.0	133	121	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks (L) Side Gate - Scratch - Large / Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Side Gate - Modified - Large / (L) Side Gate - Modified - Large / (R) Side Gate - Scratch & Dent - Large / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Fender, Molding - Crack, Gap - Small / Bonnet, Headlight - Scratch - Large / (L) Front Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Large</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no tools/sunvisor light issue/ possible flooding/ with jack and spare tire/ with LTO plate and warranty booklet/</p>