

General Information

Date & Time: 15, Dec, 2025 10:27

Make	Nissan	Model	Terra
YOM	2019	Odo Meter Reading	86,026
Registration No.	ZAB8367	Chassis No.	MNTJCAD23Z0008804
CC	2.5	Transmission	M/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.0	109	109	115
2	Boot Lid	110.3	117	97	117
3	Roof	113.5	92	95	123/144
4	Left Front Fender	116.6	115	122	113
5	Left Front Door	133.0	141	147	111
6	Center Panel Left				
7	Left Rear Door	116.3	122	122	105
8	Left Back Panel	134.0	115	145	142
9	Right Front Fender	117.0	111	126	114
10	Right Front Door	106.0	100	107	111
11	Center Panel Right				
12	Right Rear Door	137.0	152	129	130
13	Right Back Panel	112.6	119	113	106

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small</p>	<p>Remarks (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Small / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Roof - Dent - Small / Bonnet, Headlight - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Unusual sound when pressing the clutch pedal. Without warranty booklet, jack, tools and seat cover. With spare tire. 1 key. With LTO plate.</p>