


General Information

Date & Time: 13, Dec, 2025 11:05

Make	Mitsubishi	Model	Xpander
YOM	2023	Odo Meter Reading	50,948
Registration No.	NIM3882	Chassis No.	MK2LRNC1WPN01770
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	101	106	140
2	Boot Lid	87.0	81	89	91
3	Roof	113.3	100	90	123/140
4	Left Front Fender	150.3	153	148	150
5	Left Front Door	102.7	98	113	97
6	Center Panel Left				
7	Left Rear Door	112.0	101	106	129
8	Left Back Panel	192.0	165	196	215
9	Right Front Fender	90.4	86	90	96
10	Right Front Door	101.5	110	99	96
11	Center Panel Right				
12	Right Rear Door	246.3	296	215	228
13	Right Back Panel	118.0	109	103	142

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

