

General Information

Date & Time: 15, Dec, 2025 15:52

Make	Mazda	Model	Mazda 3
YOM	2019	Odo Meter Reading	42,202
Registration No.	NEI4436	Chassis No.	JM8BN14A0K1247024
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.9	117	93	150
2	Boot Lid	125.2	98	179	99
3	Roof	73.6	76	72	76/71
4	Left Front Fender	122.0	127	130	109
5	Left Front Door	96.8	100	98	93
6	Center Panel Left				
7	Left Rear Door	96.0	98	97	94
8	Left Back Panel	552.3	517	619	521
9	Right Front Fender	138.6	135	140	141
10	Right Front Door	98.6	100	97	100
11	Center Panel Right				
12	Right Rear Door	135.0	140	134	131
13	Right Back Panel	146.6	148	149	143

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / Dashboard - Traces of Adhesive Tape - Yes / Steering Wheel - Worn, Peel, Crack - Small / Ceiling - Grime - Small / Knobs - Worn, Peel, Crack - Small</p>	<p>Remarks (L) Rear Fender - Repair Traces - Yes / Roof - Repair Traces - Yes / Roof - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / Overall Exterior - Faded(Color, Gloss) - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire, No Tools and Jack and Warranty booklet, No spare key, worn tires and Sparetire, Scratch and Crack Tail light and Headlight, foul smell, plate and room light issue.</p>