

General Information

Date & Time: 22, Dec, 2025 14:06

Make	Mitsubishi	Model	Mirage
YOM	2025	Odo Meter Reading	1,133
Registration No.	NEZ3696	Chassis No.	PAEA13RJSRA001277
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	127.0	128	125	128
2	Boot Lid	115.6	105	111	131
3	Roof	105.5	102	107	103/110
4	Left Front Fender	108.3	114	102	109
5	Left Front Door	109.0	111	106	110
6	Center Panel Left				
7	Left Rear Door	107.3	109	100	113
8	Left Back Panel	118.3	122	124	109
9	Right Front Fender	104.3	103	103	107
10	Right Front Door	108.6	110	106	110
11	Center Panel Right				
12	Right Rear Door	107.0	110	102	109
13	Right Back Panel	113.6	107	115	119

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks (R) Rear Door, Molding - Dent - Small / (R) Front Door, Molding - Dent - Small / Bonnet, Headlight - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no tools/ with jack and sparetire/ with warranty booklet and LTO plate/</p>