

General Information

Date & Time: 16, Jan, 2026 08:32

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	10,795
Registration No.	NFM8787	Chassis No.	PAEL65MYSRB024614
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.6	127	92	104
2	Boot Lid	317.9	145	737	72
3	Roof	70.3	66	71	76/69
4	Left Front Fender	89.1	89	97	82
5	Left Front Door	71.5	76	70	69
6	Center Panel Left	86.1	85	92	81
7	Left Rear Door				
8	Left Back Panel	109.0	113	107	107
9	Right Front Fender	76.0	84	72	72
10	Right Front Door	76.7	68	76	87
11	Center Panel Right	83.9	99	78	75
12	Right Rear Door				
13	Right Back Panel	111.7	100	144	91

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / Trim Other - Grime - Small / Ceiling - Grime - Small</p>	<p>Remarks (L) Center Panel - Scratch & Dent - Small / (L) Front Door, Molding - Scratch & Dent - Small / Front Panel - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / (R) Side Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / Rear Gate - Scratch & Dent - Medium / (L) Side Gate - Scratch & Dent - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare key, no spare tire, no tools & jack, no warranty and manual booklet, no reverse camera, scratches on taillight, reverse light issue.</p>