

General Information

Date & Time: 22, Dec, 2025 11:09

Make	Mitsubishi	Model	XForce
YOM	2025	Odo Meter Reading	16,501
Registration No.	NKE6415	Chassis No.	MK2XTGR1WSN01010
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	167.3	174	162	166
2	Boot Lid	122.3	118	131	118
3	Roof	106.7	99	119	100/109
4	Left Front Fender	134.6	135	120	149
5	Left Front Door	150.0	146	152	152
6	Center Panel Left				
7	Left Rear Door	154.6	155	149	160
8	Left Back Panel	141.0	143	145	135
9	Right Front Fender	127.3	128	126	128
10	Right Front Door	149.0	152	150	145
11	Center Panel Right				
12	Right Rear Door	147.3	154	136	152
13	Right Back Panel	132.0	137	128	131

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Rear Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	Remarks (L) Front Fender - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / (L) Front Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with warranty booklet/ with jack and spare tire/ no tools / with LTO plate