

General Information

Date & Time: 16, Jan, 2026 13:26

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	13,986
Registration No.	NKF2536	Chassis No.	PAEL65MYSRB024300
CC	2.2	Transmission	M/T
Fuel Type	Gas	Type of Body	FB Body
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	96.8	98	100	93
2	Boot Lid	89.0	103	101	63
3	Roof	92.3	110	77	93/90
4	Left Front Fender	90.6	94	104	74
5	Left Front Door	91.9	99	89	88
6	Center Panel Left	82.6	70	96	82
7	Left Rear Door				
8	Left Back Panel	113.6	121	92	128
9	Right Front Fender	86.3	91	93	74
10	Right Front Door	75.3	85	68	73
11	Center Panel Right	90.5	71	82	119
12	Right Rear Door				
13	Right Back Panel	106.6	115	101	104

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Medium / (R) Front Trim - Grime - Medium</p>	<p>Remarks (L) Side Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Rust, Corrosion - Medium / Rear Gate - Scratch - Medium / (R) Side Gate - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Small / Front Panel - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Center Panel - Scratch - Small / Roof - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Medium</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with spare tire no tools & jack, no spare key, no reverse camera, no manual & warranty booklet, scratches on taillight and headlight, issue on shifting in reverse and 5th gear.</p>