

General Information

Date & Time: 12, Jan, 2026 10:54

Make	Mitsubishi	Model	L300
YOM	2025	Odo Meter Reading	3,109
Registration No.	NKG4324	Chassis No.	PAEL65MYSRB026710
CC	2.2	Transmission	M/T
Fuel Type	Diesel	Type of Body	FB Body
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.0	132	86	82
2	Boot Lid	71.3	92	65	58
3	Roof	72.8	64	79	76/73
4	Left Front Fender	78.8	74	80	83
5	Left Front Door	68.0	69	70	65
6	Center Panel Left	79.3	78	78	82
7	Left Rear Door				
8	Left Back Panel	89.0	81	89	96
9	Right Front Fender	82.2	81	88	77
10	Right Front Door	69.6	74	68	66
11	Center Panel Right	83.2	85	85	80
12	Right Rear Door				
13	Right Back Panel	100.0	88	91	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Small / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal / (R) Front Seat - Grime - Minimal</p>	<p>Remarks Front Panel - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Side Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Small / (L) Side Gate - Scratch & Dent - Small / Cargo Bed Floor - Scratch - Medium / (L) Center Panel - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes</p>

Inspector Notes
<p>with LTO plate, with warranty and manual booklet, with spare tire, with spare key, with incomplete tools and jack, no reverse light, scratches on taillight, ac switches missing.</p>