

## General Information

Date & Time: 20, Dec, 2025 14:03

<b>Make</b>	Mitsubishi	<b>Model</b>	Xpander
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	30,620
<b>Registration No.</b>	NKI8364	<b>Chassis No.</b>	MK2LNNC1WSN00043
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Wagon
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.3	100	92	106
2	Boot Lid	82.9	88	84	77
3	Roof	102.6	115	104	96/95
4	Left Front Fender	87.1	86	86	89
5	Left Front Door	93.9	92	93	97
6	Center Panel Left				
7	Left Rear Door	91.0	95	88	91
8	Left Back Panel	102.3	102	108	97
9	Right Front Fender	88.2	87	90	88
10	Right Front Door	92.0	92	94	90
11	Center Panel Right				
12	Right Rear Door	85.8	86	82	90
13	Right Back Panel	96.7	96	100	95

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

