

## General Information

Date & Time: 15, Dec, 2025 08:55

<b>Make</b>	Mitsubishi	<b>Model</b>	L300
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	17,749
<b>Registration No.</b>	NKM5240	<b>Chassis No.</b>	PAEL65MYSRB028193
<b>CC</b>	2.2	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	FB Body
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	94.0	126	76	80
2	Boot Lid	105.8	113	106	99
3	Roof	76.5	60	102	70/74
4	Left Front Fender	79.5	76	84	78
5	Left Front Door	78.2	70	67	98
6	Center Panel Left	81.4	87	75	82
7	Left Rear Door				
8	Left Back Panel	124.0	102	107	163
9	Right Front Fender	83.7	75	90	86
10	Right Front Door	69.5	74	67	67
11	Center Panel Right	90.2	93	87	91
12	Right Rear Door				
13	Right Back Panel	134.0	166	117	119

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

