

General Information

Date & Time: 13, Jan, 2026 15:01

Make	Mitsubishi	Model	Mirage
YOM	2024	Odo Meter Reading	7,732
Registration No.	DBQ3526	Chassis No.	PAEA13MJRRA018787
CC	1.2	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.3	125	110	111
2	Boot Lid	119.0	106	138	113
3	Roof	110.2	107	101	117/116
4	Left Front Fender	105.3	109	107	100
5	Left Front Door	107.0	106	106	109
6	Center Panel Left				
7	Left Rear Door	106.6	110	108	102
8	Left Back Panel	116.6	116	120	114
9	Right Front Fender	117.3	108	122	122
10	Right Front Door	111.3	108	111	115
11	Center Panel Right				
12	Right Rear Door	104.8	104	100	111
13	Right Back Panel	107.6	103	109	111

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Crack, Gap - Large / (L) Front Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no tools and spare tire/ possible flooding/ with jack/ with warranty booklet and LTO plate/</p>