

General Information

Date & Time: 19, Jan, 2026 10:57

Make	Mitsubishi	Model	Strada
YOM	2023	Odo Meter Reading	34,196
Registration No.	LAL7716	Chassis No.	MMBJKL10PH048738
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.6	122	110	145
2	Boot Lid	92.2	90	91	96
3	Roof	121.7	111	104	133/139
4	Left Front Fender	110.1	131	89	111
5	Left Front Door	106.5	96	110	114
6	Center Panel Left				
7	Left Rear Door	109.6	113	101	115
8	Left Back Panel	100.8	92	106	105
9	Right Front Fender	104.8	88	111	116
10	Right Front Door	108.3	106	116	103
11	Center Panel Right				
12	Right Rear Door	115.0	120	117	108
13	Right Back Panel	107.0	106	110	105

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Overall Interior - Smell - Yes / Dashboard - Worked - Minimal / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / Rear Seat - Grime - Medium / Ceiling - Grime - Minimal</p>	<p>Remarks Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Side Gate - Scratch & Dent - Small / Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Side Gate - Scratch & Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Medium / Roof - Scratch - Medium / Cargo Bed Floor - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Air Conditioner - Function - Weak / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate, with reverse camera, with manual booklet, issue on left front tire, issue on aircon, scratches on taillight and headlight, issue on reverse light, possible flooded.</p>