

General Information

Date & Time: 13, Jan, 2026 15:58

Make	MG	Model	G50 Plus
YOM	2025	Odo Meter Reading	16,490
Registration No.	MBD9013	Chassis No.	LSKK4BC17SD040871
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	151.0	154	153	146
2	Boot Lid	112.6	124	102	112
3	Roof	148.2	145	143	153/152
4	Left Front Fender	125.6	128	126	123
5	Left Front Door	141.0	144	141	138
6	Center Panel Left				
7	Left Rear Door	130.6	132	126	134
8	Left Back Panel	125.3	148	118	110
9	Right Front Fender	130.0	128	121	141
10	Right Front Door	136.3	127	144	138
11	Center Panel Right				
12	Right Rear Door	140.6	139	143	140
13	Right Back Panel	133.6	134	129	138

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / Sunvisor, Sunglass Holder - Grime - Small / Ceiling - Grime - Small / (R) Rear Trim - Cut, Crack - Minimal / (L) Rear Trim - Cut, Crack - Minimal / (R) Front Trim - Cut, Crack - Small / (L) Front Trim - Cut, Crack - Small</p>	<p>Remarks (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet, jack and tools, with spare tire, with LTO plate, scratches on headlight and tail light</p>