

General Information

Date & Time: 13, Jan, 2026 15:38

Make	Hyundai	Model	Stargazer
YOM	2023	Odo Meter Reading	45,611
Registration No.	NIO2476	Chassis No.	MF3NB81DEPJ017117
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	MPV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	126.0	132	127	119
2	Boot Lid	92.5	88	92	98
3	Roof	104.0	106	104	101/105
4	Left Front Fender	99.2	86	110	102
5	Left Front Door	117.6	130	113	110
6	Center Panel Left				
7	Left Rear Door	117.6	118	115	120
8	Left Back Panel	114.6	122	112	110
9	Right Front Fender	106.4	121	108	90
10	Right Front Door	112.3	104	113	120
11	Center Panel Right				
12	Right Rear Door	111.3	111	111	112
13	Right Back Panel	114.0	113	114	115

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Worked - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no warranty booklet/ no tools/ possible flooding/ with jack and spare tire/ with LTO plate/</p>